

Notice to Mariners

3493 Vancouver Harbour, Western Portion/ - New Edition - 01-DEC-2006 - NAD 1983 28-NOV-2008 or 2008-11-28

Delete depth of 2.6 metres 49°16'19.5"N 123°06'43.6"W

Delete depth of 1.7 metres 49°16'21.0"N 123°06'35.1"W

Delete depth of 1.7 metres 49°16'21.0"N 123°06'35.1"W

Add area under reclamation (2008)

joining

49°16'18.8"N 123°06'40.9"W

49°16'19.3"N 123°06'41.2"W

49°16'18.7"N 123°06'44.0"W

49°16'19.0"N 123°06'44.8"W

49°16'19.4"N 123°06'44.4"W

49°16'21.0"N 123°06'38.3"W

and

49°16'20.9"N 123°06'34.3"W

This notice might affect Electronic Navigation Chart: CA570073

3459 Approaches to/Approches à Nanoose Harbour - New Edition - 24-OCT-1997 - NAD 1983 07-NOV-2008 or 2008-11-07

Add depth of 3 metres 49°17'16.4"N 124°08'01.9"W

Add depth of 4.9 metres 49°17'21.5"N 124°05'26.3"W

Add depth of 7 metres 49°17'20.2"N 124°04'08.2"W

Add depth of 6.2 metres 49°17'23.5"N 124°03'59.6"W

Add depth of 2.6 metres 49°16'41.7"N 124°06'31.7"W

Add depth of 8.2 metres 49°16'21.9"N 124°06'39.5"W

Delete depth of 12.8 metres 49°16'12.7"N 124°05'10.8"W

Add depth of 3.6 metres 49°16'12.7"N 124°05'11.5"W

Delete depth of 11 metres 49°17'08.0"N 124°05'31.7"W

Add depth of 8.4 metres 49°17'09.2"N 124°05'30.4"W

Add depth of Rock Awash 49°16'39.2"N 124°06'32.9"W

This notice might affect Electronic Navigation Chart: CA570193

3311 Howe Sound to/à Pender Harbour - Sheet 3 - New Edition - 31-DEC-1993 - NAD 1983

Add depth of 0.1 metre and legend Rep (2008) 49°21'51.8"N 123°29'13.8"W

3311 Port Moody to/à Howe Sound - Sheet 1 - New Edition - 31-DEC-1993 - NAD 1983

Add depth of 0.1 metre and legend Rep (2008) 49°21'51.8"N 123°29'13.8"W

3526 Howe Sound - New Edition - 01-JUL-2005 - NAD 1983 12-DEC-2008 or 2008-12-12

Add depth of 0.1 metre and legend Rep (2008) 49°21'51.8"N 123°29'13.8"W

This notice might affect Electronic Navigation Chart: CA470004

Active Notices to Shipping

Last Active Notship Created: 14 Jan 2009 At 1531

P-0102(2009) FRASER RIVER - ANNACIS CHANNEL

Activated:1531 14 Jan 2009

The Annacis Swing Bridge is closed to marine traffic until further notice.

P-0099(2009) OAK BAY - MAYOR CHANNEL

Activated:1113 14 Jan 2009

ROBSON REEF DAYBEACON UL5104 permanently changed from port bifurcation daybeacon to port daybeacon.

P-0098(2009) JOHNSTONE STRAIT

Activated:1107 14 Jan 2009

WEST REDONDA ISLAND LL527 reported extinguished.

P-0095(2009) STRAIT OF GEORGIA - LAMBERT CHANNEL

Activated:1643 13 Jan 2009

HORNBY ISLAND WHARF P37 UL5294 reported submerged at high tide.

Mariners are requested to avoid the area between buoy Y33 and buoy Y34, in the vicinity of Usatzes Point, due to oil recovery operations until further notice.

P-0091(2009) FALSE CREEK

Activated:1046 13 Jan 2009 Cancel Notship(s) P-0088(2009)
Drilling operations will take place 24 hours a day from 0700 PST Jan 13 until 2400 PST Jan 16, 2009 in a line south from David Lam Park.

The tug "Keluk" and barge will monitor VHF channel 16.

Mariners are advised to use caution while transiting the area.

P-0075(2009) CHATHAM SOUND - BROWN PASSAGE

Activated:1744 11 Jan 2009

HANMER ROCK LIGHT AND WHISTLE BUOY D57 LL753 reported off advertised position.

P-0064(2009) TSEHUM HARBOUR

Activated:1215 10 Jan 2009 Cancel Notship(s) P-0048(2009),P-0063(2009)

The private flashing green light at the end of the Van Isle Marina breakwater at the entrance to Tsehum Harbour, position 48 40.267N 123 24.299W (chart datum unknown) reported extinguished.

P-0043(2009) HARO STRAIT - SAN JUAN ISLAND

Activated:0311 08 Jan 2009
LIME KILN LL222 LIGHT reported extinguished.

P-0018(2009) BARKLEY SOUND - UCLUELET

Activated:0344 04 Jan 2009
CAROLINA CHANNEL LIGHT AND WHISTLE BUOY Y42 LL136 reported extinguished.

P-0012(2009) HARO STRAIT

Activated:1558 02 Jan 2009
FORREST ISLAND LL225.4 characteristics permanently changed to flashing white every four seconds.

The light is atop of a white cylindrical tower. The red band at top of tower has been removed.

Any objections must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

P-1856(2008) WEST COAST - VANCOUVER ISLAND

Activated:0303 25 Dec 2008
JUAN DE FUCA TRAFFIC LANE SEPARATION LIGHT
BUOY J LL180.8 reported extinguished.

P-1675(2008) STRAIT OF GEORGIA

Activated:1442 20 Nov 2008
A subsurface mooring buoy has been established in position
49 50.136N 124 52.128W (WGS 84) 33 metres below the surface and will
remain until May 2009

P-1667(2008) STRAIT OF GEORGIA

Activated:1623 19 Nov 2008
A subsurface mooring buoy has been deployed in position:
49 01.649N 123 25.461W (Nad unknown)
at a depth of 43 metres below the surface and will remain until May 2009.

P-1661(2008) BAYNES SOUND

Activated:1020 19 Nov 2008
A yellow wave buoy, 1 metre in diameter, with yellow flashing light (5 flashes
every 20 seconds) has been deployed northeast of Buckley Bay in position:
49 32.005N 124 50.474W (WGS84)

Mariners are requested to maintain a 100 metre clearance of this buoy.

The buoy will remain on station for 3 months.